

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

1. Name of the Officer : NEETHU. A
2. Name of the School : Nilgiri Public School, Nombikkode, Elappully G.P.
3. Location with name of Education District/Sub. District : Nombikkode, Chittur Sub District
4. Classification of Building as specified in Column 4 of the application for fitness certificate and size :
RCC- GF-11 Room (6.12x6.12x3.6m)- Class Room
RCC-GF-1 (6.25x5.5x3.6)-Class Room
RCC-GF-2 Room(6.25x5.15x3.6)
RCC-GF-1 Room (6.12x6.12x3.6m)-Principle
RCC-FF-7 Room (6.12x6.12x3.6m)-Class Room
RCC-FF- 1 Room (6.45x5.0m)
RCC-FF- 2 Room (6.25x5.55x3.6m)
RCC-FF- 1 Room (6.25x5.15x3.6m)
RCC-FF-3Room (6.12x6.12x3.6m)-Lab
RCC-FF-2 Room (6.12x6.12x3.6m)-Library
RCC-SF-7 Room (6.12x6.12x3.6m)-Class Room
RCC-SF- 1 Room (6.45x5.0m)
RCC-SF- 2 Room (6.25x5.55m)
RCC-SF- 1 Room (6.25x5.15m)
5. Period for which the certificate is issued : 2026 – 2027 Academic Year
6. Nature of defects, if any
 - (a) Foundation and basement : NIL
 - (b) Super structure : NIL
 - (c) Doors and Windows : NIL
 - (d) Wood work wrought and put up : NIL
 - (e) Roof : NIL
 - (f) Flooring : NIL
 - (g) Miscellaneous (Cracks, etc.) : NIL
7. Any major defects noticed which will render the building unsafe in any manner : NIL
8. Whether maintenance works have been done properly : Yes
9. Whether the structure is sound or not for conducting classes : Yes, the structure is sound under normal weather condition.

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observation if deemed necessary for the certificate may be furnished separately this certificate.

Additional Notes:

- 1. This certificate is applicable only to safety related to civil construction. Seperate certificates for fire and safety and safety of electrical installations, electrical lines/conduits shall be obtained from the concerned departments.**
- 2. Maintenance of the school premises should be done periodically. The inspecting officer is not liable for any unfortunate accidents in the school premises due to lack of security or periodic maintenance.**
- 3. This certificate is only for the structural safety of the classrooms mentioned in this certificate. It does not cover safety in laboratories, kitchens, etc.**
- 4. For any new construction in the school compound, should be intimated and a permit should be obtained from LSGI. Safety measures such as barricades must be ensured..**


CERTIFICATE

Certified that the school building was inspected by me on 29.05.2026 and found to be fit to conduct classes, for the period 2026-27 Academic year for the reasons stated above.

Place : Elappully

Date : 29.05.2026

(Seal)



[Handwritten Signature]

Assistant Engineer . A
PEN: 941525
Assistant Engineer
LID & EW (LSGD)
Elappully Section